


Northeast Reliability Interconnect

Bangor Hydro-Electric Company




U.S.G.S. data: Alligator Lake Quadrangle, 1998

Existing Conditions 2A Existing view looking southeast from the top of Eagle Mountain. Stud Mill Road, seen in the center of the photograph, is approximately 2.0 miles from the viewer. Photograph by TJD&A, September 29, 2004.



Northeast Reliability Interconnect

Bangor Hydro-Electric Company



U.S.G.S. data: Alligator Lake Quadrangle, 1998

Photosimulation 2B Photosimulation looking southeast from the top of Eagle Mountain toward the proposed utility corridor on the north side of Stud Mill Road. Photograph by TJD&A, September 29, 2004.